



## 图书基本信息

- 书名: <<HSE警示录>>
- 13位ISBN编号:9787502183486
- 10位ISBN编号:7502183485
- 出版时间:2011-3
- 出版时间:石油工业出版社
- 作者:中国石油海外勘探开发公司编
- 页数:244


版权说明:本站所提供下载的PDF图书仅提供预览和简介,请支持正版图书。

更多资源请访问:http://www.tushu007.com



## 内容概要

继2010年7月印发《HSE警示录》之后,又推出了《HSE警示录(二)》。 书中的47起事故事件就发生在近两年,发生在我们身边。 事故的当事人、受害人有的是我们的同事、朋友,有的是为我们提供服务的承包商、分包商员工。 一次小小的疏忽、一个简单的错误、一个不安全的行为,就可能酿成一起事故,造成无法挽回的人身 伤亡或重大财产损失,毁掉个人的生命、家庭的幸福、企业的安定、社会的和谐。 教训之深刻,后果之惨重,令我们痛心,更令我们反思。





## 书籍目录

Group 1 Caught In, Under or Between Worker Caught Between Truck and Skid Pump Foreman Pressed by Heavy Electrical Cabinet Pipe Yard Worker Suffered Thumb Injury Fingers Crushed by Roller Hand Pinched during Assembling Work Group 2 Cut, Puncture, Scrape Finger Joint Lost When Shutting off Wood Cutting Machine Group 3 Explosions or Burns Vacuum Truck Explosion Inflammation during Tanker Loading **Refrigerator Truck Explosion** Burn by Fire from Gas Leakage Automotive Technician Injured in Tire Explosion Driver Injured by Tyre Rupture **Battery Explosion Operator Burnt by Steam** Burn by Hot Formation Water Group 4 Exposure: Electrocution Worker Killed by Overhead Power Line Group 5 Exposure: Noise, Pressure, Chemical, **Biological**, Vibration Bulldozer Operator Attacked by Wasps Escape from H2S Poisoning Bathroom Cleaner Suffered Eye Injury Group 6 Falls From Height Assistant Welder Fell From Height Security Guard Fell into a Cellar Group 7 Overexertion/Strain Back Injured When Lifting Boxes Group 8 Slips and Trips(at the same height) Burn after Slip in Kitchen Group 9 Struck By Driller Assistant Hit by Pipe Wrench Hand Injury during Casing Running Construction Worker Hit by Tent Frame Operator Struck by Broken Knuckle Joint Leg Injured by Swinging Pipe Welder Injured By Plate Falling from Drill Floor Group 10 Vehicle Crashes Fatal Traffic Accident at Field Bypass Road Collision Between a Dump Truck and a Fuel Tanker Fatal Traffic Accident Due to Overspeeding Worker Killed When Sheltering under Truck





Security Patrolling Vehicle Accident Rollover Accident during Rig Move Group 11 Non-injurious Accident Exploratory Well Blowout during Production Testing Pipeline Leakage Oil Spilled from Vent Pond Pollution Resulted from Oil Well Blow-out Explosion of Buffer Tank in Metering Station Fire from Tanker Welding Fire Incident from Welding Operation Meeting Room Fire Scrap Yard Fire **Bakery Container Fire** Fiber Optical Cable Damaged by Excavator Group 12 Near Miss Excavation Near Miss Due to Non-compliance





## 版权说明

本站所提供下载的PDF图书仅提供预览和简介,请支持正版图书。

更多资源请访问:http://www.tushu007.com